




View of channel upstream of upper reservoir.



Upper reservoir dam.





Spillway at the upper reservoir.



View down the spillway at the upper reservoir.





View looking upstream from lower to upper reservoir. There was evidence of a channel between the two reservoirs.




View looking downstream into the lower reservoir.





Close up view of channel about 20 feet above the lower reservoir. Picture shows sandy bed and eroded banks.




View of spillway at the lower reservoir.





Spillway at lower reservoir dam is at right side of picture.



View looking downstream from center of lower reservoir's dam.